



## Voltages with fuse removed



This applies to PD power centers and fuseboards with a blown fuse indicator LED







There are 2 types of blown fuse detectors one has an amplifier providing very very low current to the device with the blown fuse <30 microamps

The non amplified one limits the current to < 5 ma